## CORNER HISTORY:

CORNER FILE CODE: T6S-R9W-L-21

ORIGINAL USPLS SURVEY: Corner established by Jacob Fowler, Dec. 21(?), 1805 "Post".

COUNTY SURVEYOR'S BOOKS: Book 1 P. 21: Isaac Adams WCS Dec. 7, 1853 (Mon. not identified) Book 3 P.

90: J. H. Wilke WCS Dec. 6, 1906 (Sec. Line run but no mention of this corner)"

OTHER SURVEYS AND PLATS: 1994 INDOT survey (K. E. Jackson) tied in and referenced a 1-112" rebar 2" below grade. Mr. Jackson's survey report states that the rebar agrees with monuments found in Groeninger's Place Subdivision, but due to o variety of other monuments found in the area, Mr. Jackson reported uncertainties of approximately 41' N, 19' S, 10' W, and 20' E.

A plot of survey by Ralph A. Easley (Doc. 2000R-000157) shows a 1-1/2" rebar found.

<u>VERIFICATION OF CORNER POSITION:</u> September, 2002: The 1-1/2" iron pin shown was found in place, consistent with reference ties from the 1994 INDOT route survey.

June, 2005: The 1-1/2" iron pin shown was found in place, consistent with reference ties. Reference ties were measured using a tape. Due to the high volume of traffic on S.R. 261 only one point was measured on the west side of S.R. 261, that was the PK Nail on a utility pole 64.73' away.

Perry E. Jones 9/11/02

Brian Schnur and Dan Grady 6/17/05